## STEP 1

► Plug in the card reader. Go to START menu and select "Control Panel"


STEP 2

► Click on "Hardware and Sound"

STEP 3
► Click on "Device Manager"


STEP 4
► Find and double click on "eHome Infrared Receiver (USBCIR)"

STEP 5
► Go to Driver tab

eHome Infrared Receiver (USBCIR) Properties

General | Driver | Details

eHome Infrared Receiver (USBCIR)

Device type:	Universal Serial Bus controllers
Manufacturer:	Microsoft
Location:	Port_#0005.Hub_#0004

Device status

This device cannot start. (Code 10)

[OK]   [Cancel]

STEP 6
► Click on "Update Driver…"

eHome Infrared Receiver (USBCIR) Properties

General | Driver | Details

eHome Infrared Receiver (USBCIR)

Driver Provider:	Microsoft
Driver Date:	21/06/2006
Driver Version:	6.1.7100.0
Digital Signer:	Microsoft Windows

Button	Description
Driver Details	To view details about the driver files.
Update Driver...	To update the driver software for this device.
Roll Back Driver	If the device fails after updating the driver, roll back to the previously installed driver.
Disable	Disables the selected device.
Uninstall	To uninstall the driver (Advanced).

[OK]   [Cancel]

STEP 7
► Click on "Browse my computer for driver software"

STEP 8
► Click on "Let me pick from a list..", no need for selecting location

STEP 9
► Select "USB Composite Device" and press Next button. Windows 7 will install the driver automatically.

STEP 10
► Once the memory card is inserted into card reader a new drive should appear in Windows "Computer" folder.